

Link do produktu: <https://diesel-masz.pl/rozzrusznik-landini-massey-ferguson-mccormick-renault-3597372m2-lrs301-nsb530-p-2837.html>



ROZRUSZNIK LANDINI MASSEY FERGUSON MCCORMICK RENAULT 3597372M2, LRS301, NSB530

Cena brutto	960,00 zł
Cena netto	780,49 zł
Czas wysyłki	w ciągu 24-48 godzin
Numer katalogowy	3597372M2



Opis produktu

ROZRUSZNIK

LANDINI:

4560V, 5560F, 5560L, 5860, 6060, 6060F, 6060L, 6060V, 5860, 55GTP, 60GTP, Blizzard 50, Blizzard 60, C6000, 6000, Trekker 55F

MASSEY FERGUSON:

168, 174, 174C, 174F, 174S, 174V, 175, 175S, 184, 184F, 184S, 185, 188, 194, 194C, 194F, 194S, 1004, 1004T, 1007, 1014, 1024, 1080, 1085, 1100, 1104, 1105, 1114, 1134, 1135, 1200, 1250, 265, 265S, 273, 274, 274C, 274CF, 274S, 274SK, 275, 275E, 285, 285 (USA), 285S, 290, 290E, 293, 294, 294C, 294S, 265, 362, 362N, 365, 367CF, 372N, 373, 373LX, 373S, 374AP, 374AP(X), 374AQ, 374F, 374FP, 374FP(X), 374FQ, 374GE, 374GE(X), 374H, 374S, 374SP, 374SP(X), 374SQ, 374V, 374VQ, 375, 375E, 376C, 376CF, 376XCF, 377, 382N, 383, 383LX, 383S, 384AP, 384AP(X), 384AQ, 384F, 384FP, 384FP(X), 384FQ, 384GE, 384GE(X), 384S, 384SP, 384SP(X), 384SQ, 384V, 384VQ, 390, 390E, 393, 393LX, 393S, 393TLX, 394AP, 394AP(X), 394AQ, 394C, 394F, 394FP, 394FP(X), 394FQ, 394GE, 394GE(X), 394H, 394S, 394SP, 394SP(X), 394SQ, 394TAQ, 396, 396C, 396CF, 396CT, 397, 397T, 398, 399, 3050, 3055, 3060, 3065, 3065S, 3070, 3075, 4225, 4225HV, 4235, 4235 (USA), 4235HV, 4235HV (USA), 4245, 4245HV, 4255, 4255HV, 4260, 4265, 4270, 4325, 4325HV, 4335, 4335HV, 4345, 4345HV, 4355, 4355HV, 4360, 4365, 4370, 565, 575, 590, 592, 595, 675, 690, 698, 698T, 699, 6120, 6130, 6140, 6150

MCCORMICK:

F60, V60, V65

RENAULT:

601-4,

NUMER KATALOGOWY: 27582D, 2873D004, 3542186M91, 3546390M91, 3597371M1, 3597371M2, 3597371R2, 3930507R1, 4224325M91, 6232A, 887057M1, 887057M2, 890973M1, 893398M1, 894732M1, 898000M1, 898090M1, 95963J,

964382M1, 968296M1, 968856M1, LRS190, LRS301, NSB530, 1680065M3, 168065M3, 1691805M2, 1691805R2, 1808449M2, 1808449R2, 1868283M2, 1868283M5, 1871433M2, 1893611M91, 1893705M91, 1893705T, 27540NSB530

Produkt nowy

Gwarancja Producenta