

Dane aktualne na dzień: 09-05-2024 04:04

Link do produktu: <https://diesel-masz.pl/zestaw-naprawczy-pompy-wody-massey-ferguson-landini-4222841m91-u7lw0173-p-4538.html>



ZESTAW NAPRAWCZY POMPY WODY MASSEY FERGUSON LANDINI 4222841M91, U7LW0173

Cena brutto	299,00 zł
Cena netto	243,09 zł
Czas wysyłki	1- 2 dni Zapytaj o dokładny termin
Numer katalogowy	4222841M91



Opis produktu

ZESTAW NAPRAWCZY POMPY WODY

MASSEY FERGUSON:

4225, 4225HV, 4235, 4235HV, 4235HV, 4245, 4245HV, 4255, 4255HV, 4265, 4325, 4325HV, 4335, 4335HV, 4345, 4345HV, 4355, 4355HV, 4365, 5465, 6235, 6235HV, 6245, 6245HV, 6255, 6255HV, 6260, 6265, 6270, 6280, 6290, 6465, 6475, 6480, 7465, 7475, 7480, 8210, 8220, 8925, 8925T, 8926, 8926T, 8937, 8937T, 8939, 8939T

LANDINI:

LandPower 125, LandPower 135, LandPower 145, LandPower 165, LandPower 185, Legend 105, Legend 115, Legend 130, Legend 145, Legend 140 NG, Legend 160 NG, Legend 180 NG, Legend 125 NG TDI, Legend 135 NG TDI, Legend 145 NG TDI, Legend 165 NG TDI, Legend 185 NG TDI, Mythos 110, Mythos 115

TYP SILNIKA:

1004.40 - Perkins
1004.40T - Perkins
1004.40TW - Perkins
1004.42 - Perkins
1006.60 - Perkins
1006.60T - Perkins
1106D-E66TA - Perkins
1006.6 - Perkins
1006.60T - Perkins
1006.6T - Perkins
1106.E60TA - Perkins

NUMER KATALOGOWY: U7LW0146, U7LW0147, U7LW0157, U7LW0158, U7LW0161, U7LW0173, 4222841M91, 4223103M91, 4223739M91, 4224047M91, 4224675M91

Produkt nowy

Gwarancja Producenta